

**Report Date** 4/11/2007

**Company** G-MAN INSPECTION SERVICES, LLC  
**Address** 4811 Corkwood Lane Orlando, FL 32808  
**Thermographer** Carlos Guzman

**Customer** Sample  
**Site Address** 123 MainUSA  
**Contact Person** John Doe




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:04:11 22:25:55	
Image Name	Electrical Sub-Panel.jpg	
Emissivity	0.92	
Reflected Temperature	72.0 °F	
Object Distance	6.6 ft	

Description
Electrical sub-panel. 30A circuit breaker to water heater. Picture shows abnormal conditions in circuit (Hot breaker) by direct measurement. Unable to remove sub-panel cover at time of measurement. Recommend further evaluation by a licensed contractor.