

Report Date 5/10/2007

Company G-MAN INSPECTION SERVICES, LLC
Address 4811 Corkwood Lane Orlando, FL 32808
Thermographer Carlos Guzman

Customer Sample
Site Address 123 MainUSA
Contact Person John Doe




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:05:10 08:49:47	
Image Name	IR_0064.jpg	
Emissivity	0.95	
Reflected Temperature	78.0 °F	
Object Distance	8.0 ft	

Description
TEST Image: 1959 house, livingroom ceiling surface. Image shows poor and compressed insulation coverage. Temp. measurements are approximate.